


	R1	R2	R3	R4	S5	S6	S7	S8	T9	T10	T11	T12
pos.1	•	•	•	•	•	•	•	•	•	•	•	•
pos.2	•	•	•	•	•	•	•	•	•	•	•	•
pos.3	•	•	•	•	•	•	•	•	•	•	•	•
pos.4	•	•	•	•	•	•	•	•	•	•	•	•
pos.5	•	•	•	•	•	•	•	•	•	•	•	•
pos.6	•	•	•	•	•	•	•	•	•	•	•	•
pos.7	•	•	•	•	•	•	•	•	•	•	•	•
pos.8	•	•	•	•	•	•	•	•	•	•	•	•

	R1	R2	S1	S2	T1	T2
pos.1	•	•	•	•	•	•
pos.2	•	•	•	•	•	•

220-380 V 50-60HZ
MIG 250-C



415-440 V 50-60HZ
MIG 250-C

	R1	R2	R3	R4	S5	S6	S7	S8	T9	T10	T11	T12
pos.1	•											
pos.2		•										
pos.3			•									
pos.4				•								
pos.5					•							
pos.6						•						
pos.7							•					
pos.8								•				

	R1	R2	S1	S2	T1	T2
pos.1	•					
pos.2		•				