
Document <i>Documento</i>	Firmware upgrade history <i>Storico aggiornamenti Firmware</i>
Model <i>Modello</i>	SYNSTAR 350 TS
Code <i>Articolo</i>	8037900
Firmware version <i>Versione firmware</i>	7
Issue date <i>Data di rilascio</i>	12/02/2024

ITALIANO.....	2
ENGLISH.....	3

ITALIANO

Aggiornamenti Firmware rel. "7"

- Aggiunta nuova lingua: polacco

Aggiornamenti Firmware rel. "6"

- Aggiornamenti interni

Aggiornamenti Firmware rel. "5"

- Migliorata gestione kit RAI456

Aggiornamenti Firmware rel. "4"

- Abilitati processi short-HD e pulse-HD
- Nuove curve sinergiche short-HD e pulse-HD

Aggiornamenti Firmware rel. "3"

- Aggiornamenti interni

Aggiornamenti Firmware rel. "2"

- Aggiunto supporto per interfaccia robot RAI Art. 456
- Nuova finestra job e aggiunta tastiera virtuale
- Aggiunta modalità calibrazione
- Aggiornamenti interni

ENGLISH

Update Firmware rel. "7"

- Added new language: Polish

Update Firmware rel. "6"

- Internal improvements

Update Firmware rel. "5"

- Improved management of the RAI456 kit

Update Firmware rel. "4"

- New short-HD e pulse-HD processes unlocked
- New synergic curves short-HD and pulse-HD

Update Firmware rel. "3"

- Internal improvements

Update Firmware rel. "2"

- Added support for robot RAI interface Art. 456
- New window job and new visual keyboard added
- Calibration mode added
- Internal improvements